

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/29/2020

Submitted Date:

10/29/2020

Document Number:

693503746

**FIELD INSPECTION FORM**

Loc ID 455317 Inspector Name: Silver, Randy On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10459  
Name of Operator: EXTRACTION OIL & GAS INC  
Address: 370 17TH STREET SUITE 5300  
City: DENVER State: CO Zip: 80202

**Findings:**

25 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Carlisle, J	970-534-6006	COGCCInspections@extractionog.com	ALL INSPECTIONS

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
455304	WELL	PR	04/27/2020	OW	014-20746	Livingston S19-25-9N	PR
455305	WELL	PR	04/27/2020	OW	014-20747	Livingston S19-25-6N	PR
455306	WELL	PR	04/27/2020	OW	014-20748	Livingston S19-25-10N	PR
455307	WELL	PR	04/27/2020	LO	014-20749	Livingston S19-25-11C	PR
455308	WELL	PR	04/27/2020	OW	014-20750	Livingston S19-25-12N	PR
455309	WELL	PR	04/27/2020	OW	014-20751	Livingston S19-25-7N	PR
455310	WELL	PR	04/27/2020	OW	014-20752	Livingston S19-25-13N	PR
455311	WELL	PR	04/27/2020	LO	014-20753	Livingston S19-25-2C	PR
455312	WELL	PR	04/27/2020	OW	014-20754	Livingston S19-25-8C	PR
455313	WELL	PR	04/27/2020	OW	014-20755	Livingston S19-25-5C	PR
455314	WELL	PR	04/27/2020	OW	014-20756	Livingston S19-25-4N	PR
455315	WELL	PR	04/27/2020	LO	014-20757	Livingston S19-25-14C	PR
455316	WELL	PR	04/27/2020	OW	014-20758	Livingston S19-25-3N	PR
457254	WELL	PR	04/27/2020	OW	014-20798	Livingston S20-25-3N	PR
457255	WELL	PR	04/27/2020	OW	014-20799	Livingston S20-25-4N	PR
457256	WELL	PR	04/27/2020	LO	014-20800	Livingston S20-25-5C	PR
468824	WELL	PR	04/27/2020	OW	014-20847	Livingston S19-25-15N	PR
468825	WELL	PR	04/27/2020	LO	014-20848	Livingston S20-25-2C	PR

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	LOCATION		
Comment:	Sound walls have been removed. Electric gate at entrance to location.		
Corrective Action:		Date:	

**Equipment:**

Type: Other	# 0		corrective date
Comment:	Electric powered produced water coolers have removed from system.		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	455304	Type:	WELL	API Number:	014-20746	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	455305	Type:	WELL	API Number:	014-20747	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	455306	Type:	WELL	API Number:	014-20748	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	455307	Type:	WELL	API Number:	014-20749	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	455308	Type:	WELL	API Number:	014-20750	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	455309	Type:	WELL	API Number:	014-20751	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	455310	Type:	WELL	API Number:	014-20752	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	455311	Type:	WELL	API Number:	014-20753	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				

Facility ID:	455312	Type:	WELL	API Number:	014-20754	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR							Date:	
Corrective Action:								Date:	
Facility ID:	455313	Type:	WELL	API Number:	014-20755	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR							Date:	
Corrective Action:								Date:	
Facility ID:	455314	Type:	WELL	API Number:	014-20756	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR							Date:	
Corrective Action:								Date:	
Facility ID:	455315	Type:	WELL	API Number:	014-20757	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR							Date:	
Corrective Action:								Date:	
Facility ID:	455316	Type:	WELL	API Number:	014-20758	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR							Date:	
Corrective Action:								Date:	
Facility ID:	457254	Type:	WELL	API Number:	014-20798	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR							Date:	
Corrective Action:								Date:	
Facility ID:	457255	Type:	WELL	API Number:	014-20799	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR							Date:	
Corrective Action:								Date:	
Facility ID:	457256	Type:	WELL	API Number:	014-20800	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR							Date:	
Corrective Action:								Date:	

Facility ID: 468824	Type: WELL	API Number: 014-20847	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: PR	
Corrective Action:	Date:

Facility ID: 468825	Type: WELL	API Number: 014-20848	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: PR	
Corrective Action:	Date:

**COGCC Comments**

Comment	User	Date
Routine inspection.	silverr	10/29/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693503747	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5280399">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5280399</a>