

Inspection Photos

10/23/2020

Operator: GORDON ENGINEERING INC -
34720

Location ID: 334074
Mesa County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: GORDON ENGINEERING INC - 34720
Location ID: 334074



Photo 1: Photo taken from the west end of the location, facing northeast. Photos show surface equipment has been removed from the Location. Location and access road requiring compaction alleviation, contouring/re-grading, replacement of soils and revegetation activities.

Inspection Photos

Operator Name: GORDON ENGINEERING INC - 34720

Location ID: 334074



Photo 2: Photo taken from the west end of the location, facing southeast. Photos show surface equipment has been removed from the Location. Location and access road requiring compaction alleviation, contouring/re-grading, replacement of soils and revegetation activities.

Inspection Photos
Operator Name: GORDON ENGINEERING INC - 34720
Location ID: 334074



Photo 3: Photo shows hole/pit reaming at well location.

Inspection Photos
Operator Name: GORDON ENGINEERING INC - 34720
Location ID: 334074



Photo 4: Photo taken from the south end of the Location, facing east. Photo shows cut slopes of the location requiring contour/grading.

Inspection Photos
Operator Name: GORDON ENGINEERING INC - 34720
Location ID: 334074



Photo 5: Aerial image of the Location collected date-of-inspection via a sUAS.

Inspection Photos
Operator Name: GORDON ENGINEERING INC - 34720
Location ID: 334074



Photo 6: Aerial image showing cut slopes. See comments under photo 4.

Inspection Photos
Operator Name: GORDON ENGINEERING INC - 34720
Location ID: 334074



Photo 7: Aerial image showing pit remaining at well location. See photo 3.