

**Inspection Photos**  
**Location Name: Shable PC GK 19-99HZ**  
**Location ID: 416924**



**Photo 1 – Pumping Unit**



**Photo 2 – Tank Battery**

Inspection Photos  
Location Name: Shable PC GK 19-99HZ  
Location ID: 416924



Photo 3 – Crude Oil Tanks missing NFPA Labels

Photo 4 – Produced Water Tank missing Capacity Label