

Inspection Photos
Location Name: Ranch 1
Location ID: 317622



Photo 1 – Pumping Unit




Photo 2 – Wellhead - LOTO

Inspection Photos
Location Name: Shable PC GK 19-99HZ
Location ID: 416924




Photo 3 – Unused Chemical Tank, Stand, and Secondary Containment



Photo 4 – Pumping Unit

