

Inspection Photos
Location Name: DF Ranch PC GK 17-99HZ
Location ID: 418692



Photo 1 – Pumping Unit



Photo 2 – Wellhead - LOTO

Inspection Photos
Location Name: DF Ranch PC GK 17-99HZ
Location ID: 418692



Photo 3 – Gas Engine, Stained Soil has been cleaned up