

Inspection Photos
Operator: Kinder Morgan
API: 083-06526
Date: 10/27/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern fill slope within the interim reclamation area from the southwestern corner facing eastward. Revegetation is progressing, largely with rubber rabbitbrush, Indian ricegrass, and western wheatgrass.



Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of the reference area comprised of pinyon/juniper woodland with understory of shrubs, forbs, and grasses such as yucca, sagebrush, mountain mahogany, Indian ricegrass, purple threeawn, rock goldenrod, and ephedra.