

Inspection Photos
Operator: Kinder Morgan
API: 083-06604
Date: 10/27/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing with rubber rabbitbrush, western wheatgrass, and sideoats grama.



Photo 3. View of Russian knapweeds observed within the western project area. Approximately 200 individuals observed.



Photo 4. View of the reference area comprised of pinyon/juniper woodland with understory of shrubs, forbs, and grasses such as yucca, sagebrush, mountain mahogany, Indian ricegrass, purple threeawn, rock goldenrod, and ephedra.