

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/30/2020

Submitted Date:

10/30/2020

Document Number:

699302862

FIELD INSPECTION FORM

Loc ID 460670 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10459
Name of Operator: EXTRACTION OIL & GAS INC
Address: 370 17TH STREET SUITE 5300
City: DENVER State: CO Zip: 80202

Findings:

2 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		COGCCInspections@extractionog.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
460671	WELL	XX	01/12/2019		123-49506	Blue Bonnet 24W-20-4N	ND
460672	WELL	XX	01/12/2019		123-49507	Paintbrush 13W-20-5N	ND
460673	WELL	XX	01/12/2019		123-49508	Blue Bonnet 24W-20-12N	ND
460674	WELL	XX	01/12/2019		123-49509	Paintbrush 13W-20-7N	ND
460675	WELL	XX	01/12/2019		123-49510	Paintbrush 13W-20-10N	ND
460676	WELL	XX	01/12/2019		123-49511	Paintbrush 13W-20-6C	ND
460677	WELL	XX	01/12/2019		123-49512	Blue Bonnet 24W-20-9N	ND
460678	WELL	XX	01/12/2019		123-49513	Blue Bonnet 24W-20-1N	ND
460679	WELL	XX	01/12/2019		123-49514	Blue Bonnet 24W-20-5C	ND
460680	WELL	XX	01/12/2019		123-49515	Paintbrush 13W-20-16N	ND
460681	WELL	XX	01/12/2019		123-49516	Paintbrush 13W-20-4N	ND
460682	WELL	XX	01/12/2019		123-49517	Blue Bonnet 24W-20-8C	ND
460683	WELL	XX	01/12/2019		123-49518	Paintbrush 13W-25-12C	ND
460684	WELL	XX	01/12/2019		123-49519	Paintbrush 13W-20-3C	ND
460685	WELL	XX	01/12/2019		123-49520	Paintbrush 13W-20-9C	ND
460686	WELL	XX	01/12/2019		123-49521	Paintbrush 13W-20-8N	ND
460687	WELL	XX	01/12/2019		123-49522	Blue Bonnet 24W-20-7N	ND

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>460671</u>	Type:	<u>WELL</u>	API Number:	<u>123-49506</u>	Status:	<u>XX</u>	Insp. Status:	<u>ND</u>
Facility ID:	<u>460672</u>	Type:	<u>WELL</u>	API Number:	<u>123-49507</u>	Status:	<u>XX</u>	Insp. Status:	<u>ND</u>
Facility ID:	<u>460673</u>	Type:	<u>WELL</u>	API Number:	<u>123-49508</u>	Status:	<u>XX</u>	Insp. Status:	<u>ND</u>
Facility ID:	<u>460674</u>	Type:	<u>WELL</u>	API Number:	<u>123-49509</u>	Status:	<u>XX</u>	Insp. Status:	<u>ND</u>
Facility ID:	<u>460675</u>	Type:	<u>WELL</u>	API Number:	<u>123-49510</u>	Status:	<u>XX</u>	Insp. Status:	<u>ND</u>
Facility ID:	<u>460676</u>	Type:	<u>WELL</u>	API Number:	<u>123-49511</u>	Status:	<u>XX</u>	Insp. Status:	<u>ND</u>
Facility ID:	<u>460677</u>	Type:	<u>WELL</u>	API Number:	<u>123-49512</u>	Status:	<u>XX</u>	Insp. Status:	<u>ND</u>
Facility ID:	<u>460678</u>	Type:	<u>WELL</u>	API Number:	<u>123-49513</u>	Status:	<u>XX</u>	Insp. Status:	<u>ND</u>
Facility ID:	<u>460679</u>	Type:	<u>WELL</u>	API Number:	<u>123-49514</u>	Status:	<u>XX</u>	Insp. Status:	<u>ND</u>
Facility ID:	<u>460680</u>	Type:	<u>WELL</u>	API Number:	<u>123-49515</u>	Status:	<u>XX</u>	Insp. Status:	<u>ND</u>
Facility ID:	<u>460681</u>	Type:	<u>WELL</u>	API Number:	<u>123-49516</u>	Status:	<u>XX</u>	Insp. Status:	<u>ND</u>
Facility ID:	<u>460682</u>	Type:	<u>WELL</u>	API Number:	<u>123-49517</u>	Status:	<u>XX</u>	Insp. Status:	<u>ND</u>
Facility ID:	<u>460683</u>	Type:	<u>WELL</u>	API Number:	<u>123-49518</u>	Status:	<u>XX</u>	Insp. Status:	<u>ND</u>
Facility ID:	<u>460684</u>	Type:	<u>WELL</u>	API Number:	<u>123-49519</u>	Status:	<u>XX</u>	Insp. Status:	<u>ND</u>
Facility ID:	<u>460685</u>	Type:	<u>WELL</u>	API Number:	<u>123-49520</u>	Status:	<u>XX</u>	Insp. Status:	<u>ND</u>
Facility ID:	<u>460686</u>	Type:	<u>WELL</u>	API Number:	<u>123-49521</u>	Status:	<u>XX</u>	Insp. Status:	<u>ND</u>
Facility ID:	<u>460687</u>	Type:	<u>WELL</u>	API Number:	<u>123-49522</u>	Status:	<u>XX</u>	Insp. Status:	<u>ND</u>

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On day 10/30/2020 at approximately 1300 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Extraction Oil & Gas Inc. location:</p> <p style="text-align: right;">Blue Paintbrush Pad at</p> <p>Location #460670 in Weld County Colorado. While there, I observed a location. Location has not been constructed for oilfield operations and wells have not been drilled. During this inspection no compliance issues were observed: See attached photos. Location is muddy, weather is clear. No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	10/30/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699302863	location pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5281434