

Inspection Photos
Location Name: Stroh #2
Location ID: 323006



Production facility



Wellhead

Inspection Photos
Location Name: Stroh #2
Location ID: 323006




Emergency contact number on 10/28/2020



Emergency contact number on 10/30/2020

Inspection Photos
Location Name: Stroh #2
Location ID: 323006




Station NO. 212996
 Station Name STroh #2
 Static Range .500 DIFF. RANGE 2.50
 Temperature Range 200
 Meter Run Size _____

DATE	ORIFICE SIZE	TEST DATE
	1.250	2-18-09
	1.250	8-7-09
	1.250	8-29-18

Colorado Oil & Gas Conservation Commission
 40.3209, -104.94963, 1466.7m, 65°
 10/28/2020 13:48:53

Calibration card on 10/28/2020



Station NO. 212996
 Station Name STroh #2
 Static Range .500 DIFF. RANGE 2.50
 Temperature Range 200
 Meter Run Size _____

DATE	ORIFICE SIZE	TEST DATE
	1.250	2-18-09
	1.250	8-7-09
	1.250	8-29-18
	1.250	10-30-20

Colorado Oil & Gas Conservation Commission
 40.32093, -104.94964, 1459.0m, 8°
 10/30/2020 10:16:16

Calibration card on 10/30/2020