

# *Inspection Photos*

*Loc#418417*

*Operator: Ursa*

*Inspection Number: 692402559*

*Inspection Date: 10/16/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:

View to North from lease road, of Southwest corner of fill slope, area of concern.

October 16, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Ursa Porter B Pad Loc#418417





Photo#2:

Southwest corner of fill slope, area of concern; view from access road as entering Location

October 16, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Ursa Porter B Pad Loc#418417





Photo#3:  
Area of concern on Fill slope 6/18/20.

Photo#4:  
Area of concern on Fill slope 6/18/20.

October 16, 2020



Photo#5:  
Area of concern: Fill slope 10/16/20.



Photo#6:  
Area of concern: Fill slope 10/16/20.



Photo#7:  
Area of concern: Fill slope 10/16/20.

October 16, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Ursa Porter B Pad Loc#418417





Photo#8:  
Cracking at top of fill at Northwest side.



Photo#9:  
Cracking at top of fill at West side.

October 16, 2020





Photo#10:  
Erosion developed at NW corner of Fill.



Photo#11:  
Erosion developed at NW corner of Fill.

October 16, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Ursa Porter B Pad Loc#418417





Photo#12:  
View up cut slope to North.



Photo#13:  
View along cut slope to Southeast.

October 16, 2020