

Final Reclamation Inspection

October 30, 2020

Operator: MARKUS PRODUCTION, INC - 53790

API #: 05-123-15049

Inspection Document #: 697502141

Weld County, CO

SWSE Section 14 T6N R61W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: BABB #15-14
API #: 05-123-15049



Photo 1. COGCC GISOnline aerial imagery from 2009 during active operations illustrates some of the surface disturbance.



Photo 2. Photo taken from the entrance point off CR68, facing North. Photo illustrates recontouring has been performed but does not appear to be seeded.



Photo 3. Photo taken from the southwestern pit area, facing Northeast. Photo illustrates recontouring has been performed but does not appear to be seeded.



Photo 4. Photo taken south of the pit area, facing Northeast. Photo illustrates an area associated with the tank battery that is mostly bare soil or only growing annual vegetation.




Photo 5. Photo taken from the well location, facing South. Photo illustrates a List C Colorado noxious weed, cheatgrass, which has established throughout portions of the well location. Cheatgrass was not observed in nearby reference areas. Cheatgrass is the uniform, yellowish vegetation illustrated in the photo.




Photo 6. Photo taken from the well location, facing East. See comments under Photo 5.



Photo 7. Reference photo taken east of the pit area, facing East.