

Inspection Photos
Location Name: Hanstedt 7U-1 #3
Spill/Release Point ID: 478431



Spill/Release Point ID #478431. Fluids day lighted near yellow cone.



Area where fluids day lighted in field.

Inspection Photos
Location Name: Hanstedt 7U-1 #3
Spill/Release Point ID: 478431



Fluid in ditch along access road.



Fluid traveled along access road to pond.

Inspection Photos
Location Name: Hanstedt 7U-1 #3
Spill/Release Point ID: 478431



Close up of fluid in roadside ditch.



Fluid traveled through culvert into pond.

Inspection Photos
Location Name: Hanstedt 7U-1 #3
Spill/Release Point ID: 478431



Pond impacted by produced water.



Release terminated near outlet of outfall culvert.