

Final Reclamation Inspection

October 30, 2020

Operator: HRM RESOURCES II LLC - 10548

Location ID: 313899

Inspection Document #: 697502156

Morgan County, CO

NENW Section 8 T6N R60W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: GIVAN #1
Location ID: 313899



Photo 1. Photo taken from the associated offsite tank battery, facing West. Photo illustrates the tank battery does not meet Rule 1004 vegetative standards. Location is mostly comprised of weedy, annual vegetation (Russian thistle and Kochia).

Inspection Photos
Location Name: GIVAN #1
Location ID: 313899



Photo 2. Photo taken from the associated offsite tank battery, facing South. Photo illustrates straw wattle BMPs installed in response to a previous corrective action inspection. Vegetation shown is Kochia and Russian thistle.

Inspection Photos
Location Name: GIVAN #1
Location ID: 313899



Photo 3. Photo taken from a portion of the well location access road, facing South. Photo illustrates the access road is mostly comprised of weedy, annual vegetation (Russian thistle and Kochia).

Inspection Photos
Location Name: GIVAN #1
Location ID: 313899



Photo 4. Photo taken from the well location, facing South. Photo illustrates the well location is mostly comprised of weedy, annual vegetation (Russian thistle and Kochia).

Inspection Photos
Location Name: GIVAN #1
Location ID: 313899



Photo 5. Photo taken from the well location, facing Southeast. Photo illustrates the eastern well location has not been properly recontoured to match the surrounding landscape. The eastern portion of the well location is within a crop field.