

Inspection Photos  
Location Name: Sargent Farms 2 B  
Location ID: 318036



Photo 1 WH sign

Photo 2 WH

Inspection Photos  
Location Name: Sargent Farms 2 B  
Location ID: 318036




Photo 3 TB sign

Photo 4 TB

Inspection Photos  
Location Name: Sargent Farms 2 B  
Location ID: 318036




Photo 5 Gas Meter Run, Horizontal Heated Separator

Photo 6 card indicates current calibration