

# Final Reclamation Inspection

November 3, 2020

Operator: NOBLE ENERGY INC - #100322

Location ID: 330904

Inspection Document #: 697502162

Weld County, CO

NWNW Section 13 T4N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: EHRlich #13-22  
Location ID: 330904



**Photo 1.** Photo taken from the well location, facing North. Photo illustrates all equipment has been removed from the well location. Town of Milliken is building residential homes throughout the NW portion of Section 13 and will plan for housing development within the well location.

No noxious weed issues were observed. No stormwater erosion issues were observed.

Inspection Photos  
Location Name: EHRlich #13-22  
Location ID: 330904



**Photo 2.** Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos  
Location Name: EHRlich #13-22  
Location ID: 330904



**Photo 3.** Photo taken from the well location, facing South. See comments under Photo 1.

Inspection Photos  
Location Name: EHRlich #13-22  
Location ID: 330904



**Photo 4.** Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos  
Location Name: EHRlich #13-22  
Location ID: 330904



**Photo 5.** Photo taken from the associated offsite tank battery location. Photo illustrates the associated offsite tank battery is still active and in use for other nearby wells.

Inspection Photos  
Location Name: EHRlich #13-22  
Location ID: 330904



**Photo 6.** Photo taken from the associated offsite tank battery location, facing North. Photo illustrates no noxious weed issues were observed and no stormwater erosion issues were observed.

Inspection Photos  
Location Name: EHRlich #13-22  
Location ID: 330904



**Photo 7.** Photo taken from the associated offsite tank battery location, facing South. See comments under Photo 6.