

Inspection Photos

11/02/2020

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 423444

Garfield, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 423444



Photo 1: Photo taken from the northeast end of the location, facing northwest. Photo provides an overview of the location. All debris observed in previous inspections appear to have been removed.



Photo 2: Photo taken from the Location. Photo of noxious weed (Houndstongue) that has been treated with herbicide. Weed management appears to have been sufficient. Continue to monitor and manage Location for noxious weeds.