

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /8NENE

Location ID: 334269




Photo #2183 from entrance to location.



Photo #2181 Multiple places with debris on location.

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /8NENE

Location ID: 334269



Photo #2182 Multiple places with debris on location.



Photo #1115 from inspection #699801040 inspection conducted on 5/5/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /8NENE

Location ID: 334269



Photo #2180 Tank label weathered and not legible.

