

# Inspection Photos

API: 071-09220

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 11/3/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09220 | Date: 11/3/2020

## Inspection Photos



**Photo 1.** Facing northwest at the location. The vegetation has uniformly established.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09220 | Date: 11/3/2020

## Inspection Photos



**Photo 2.** Facing southeast at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09220 | Date: 11/3/2020

## Inspection Photos



**Photo 3.** Facing northwest toward the abandoned well marker.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09220 | Date: 11/3/2020

## Inspection Photos



**Photo 4.** Facing north toward the location. The vegetation has uniformly re-established throughout the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09220 | Date: 11/3/2020