

Inspection Photos

Operator: BP America
API: 067-07087
Date: 11/2/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing southeastward. Revegetation is progressing with crested wheatgrass, smooth brome, and western wheatgrass. Wetland vegetation growing adjacent to the project area. Canada thistles largely appear controlled, continued monitoring and treatment will be needed.



Photo 3. View of the southeastern project area from the southern corner facing northeastward.



Photo 4. View of the reference area comprised of irrigated grass field.



Photos 5/6. View of closed gates after entering (left) and leaving (right) project area.