

Inspection Photos

Operator: BP America
API: 067-07201
Date: 11/2/2020



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of area of release identified during previous reclamation inspection. No evidence of release observed.



Photo 3. View of the western project area from the northwestern corner facing southward.



Photos 4/5. View of closed gates after entering (left) and leaving (right) project area.