



6 PM

7

8

9

10

5

4

GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK

CHART NO MC MP-3000-150F 75DIV

CHART PUT ON 3-27-15 8:00 AM

LOCATION Battlement Mesa

REMARKS See back side for

Notes

3-27-15 5-27-15

3-27-15

McDonald

3-27-15 12:30 A.M.

TAKEN OFF

CHART NO MC MP-3000-150F 75DIV

CHART PUT ON 3-27-15 8:00 AM

LOCATION Battlement Mesa

REMARKS See back side for

Notes

3-27-15 5-27-15

3-27-15

McDonald

3-27-15 12:30 A.M.

TAKEN OFF

4 hrs
conducting

END
TEST

6 AM

7

8

9

Notes:

Chart recorder & Crystal gauge
located at Watson A pad. Regular pressure
gauge at Yater pad - lower elevation -
couldn't set chart at low point - No acc
of drilling org.

Paul Savala, Wehling 3-27.