

# Inspection Photos

11/04/2020

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 335928

Garfield, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335928



**Photo 1:** Photo shows cellar and equipment remaining at the PA well Location.



**Photo 2:** Photo shows cellar and equipment remaining at the PA well Location.



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 335928



**Photo 5:** Photo taken from the western interim areas of the location, facing north. Photo shows noxious weeds remaining on the Location. Previous inspections observed seed dispersal in process. It was observed in this inspection that seed dispersal appears to have been allowed to be completed, as the majority of the weed's seed heads are now bare. Weeds have not been removed as indicated by the FIRR; Unable to find evidence that sufficient weed management activities to prevent establishment and spread of noxious weeds on and from the Location have been conducted.



**Photo 6:** See comments under photo 5.