



39.82291, -108.73367, 6154.7ft, 23°
11/04/2020 03:29:43 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Douglas Creek Unit 45

API: 05-103-09311

Inspection: 700404056



39.82317, -108.73334, 6141.8ft, 3°
11/04/2020 03:30:22 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Well.

Douglas Creek Unit 45

API: 05-103-09311

Inspection: 700404056



39.823, -108.73464, 6129.1ft, 133°
11/04/2020 03:33:15 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Lease road ~150 from location.

Douglas Creek Unit 45

API: 05-103-09311

Inspection: 700404056



39.82284, -108.73452, 6138.0ft, 304°
11/04/2020 03:34:27 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Lease road ~ 150 from location.

Douglas Creek Unit 45

API: 05-103-09311

Inspection: 700404056