

Inspection Photos
Location Name: HSR-Cervi State 10-29
Location ID: 330530




Photo 1 – Pumping Unit



Photo 2 – Wellhead Sign

Inspection Photos
Location Name: HSR-Cervi State 10-29
Location ID: 330530



Photo 3 – Tank Battery



Photo 4 – Separator

Inspection Photos
Location Name: HSR-Cervi State 10-29
Location ID: 330530




Photo 5 – Gas Meter Calibration Card