

# Inspection Photos

API: 071-07543

API: 071-07716

Loc ID: 386769

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 11/3/2020



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc #386769 | Date: 11/3/2020

## Inspection Photos



**Photo 1.** Facing north at the beginning of the access road. The road has not been recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc #386769 | Date: 11/3/2020



## Inspection Photos



**Photo 2.** Facing northeast along the access road. The road has not been recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc #386769 | Date: 11/3/2020



## Inspection Photos



**Photo 3.** Facing east along the access road. There is an erosion channel along this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc #386769 | Date: 11/3/2020



## Inspection Photos



**Photo 4.** Facing east along the access road and toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc #386769 | Date: 11/3/2020



## Inspection Photos



**Photo 5.** Facing southeast toward the location. The location has not been recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc #386769 | Date: 11/3/2020



## Inspection Photos



**Photo 6.** Facing southwest toward the location. The location has not been recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc #386769 | Date: 11/3/2020



## Inspection Photos



**Photo 7.** Facing south toward the fill slope.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc #386769 | Date: 11/3/2020



## Inspection Photos



**Photo 8.** There is signs of erosion occurring off the fill slope.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc #386769 | Date: 11/3/2020



## Inspection Photos



**Photo 9.** Facing northwest toward the cut slope.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc #386769 | Date: 11/3/2020



## Inspection Photos



**Photo 10.** There is signs of erosion occurring off the cut slope.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc #386769 | Date: 11/3/2020



## Inspection Photos



**Photo 11.** Facing northwest toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc #386769 | Date: 11/3/2020



## Inspection Photos



**Photo 12.** Facing southeast toward the surrounding undisturbed reference area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc #386769 | Date: 11/3/2020