

Inspection Photos

Location Name: AURORA USX AB-67N64W /25SESE

Location #: 410103



Colorado Oil & Gas Conservation Commission
40.53909, -104.49166, 4711.0ft, 42°
11/06/2020 15:13:33

Photo #1

Aurora USX AB 25-16P (05-123-30151) Wellsite
Temporarily Abandoned | TA



Colorado Oil & Gas Conservation Commission
40.54283, -104.48959, 4696.2ft, 334°
11/06/2020 15:21:51

Photo #2

Aurora USX AB 25-16P, 10P, 11P, 25 Battery site
Abandoned: ALL Equipment Removed