

Inspection Photos

Location Name: AURORA USX AB-67N64W /25NWSE

Location #: 410102



Photo #1

Aurora USX AB 25-10P (05-123-30150) Wellsite
Temporarily Abandoned | TA



Photo #2

Aurora USX AB 25-16P, 10P, 11P, 25 Battery site
Abandoned: ALL Equipment Removed