

Inspection Photos

API#057-06462

Operator: PRM

Inspection Number: 692402622

Inspection Date: 10/21/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

Overview of exclusion area of Location to North. Insert shows emerging grasses.

October 21, 2020



Photo#2:
Overview of exclusion area Location to South.

October 21, 2020



Photo#3:

View along reclaimed portion of access road. Crimped straw mulch;

October 21, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Farleigh Oil PA Silver Spur API#057-06462-