

# *Inspection Photos*

*API#081-07750*

*Operator: PRM*

*Inspection Number: 692402630*

*Inspection Date: 10/23/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location from access road.

October 23, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: PRM PA Sheehan API#081-07750



Photo#2:

Re-vegetated area; insert is senesced thistle plant, no rosettes (1st year plants) were seen.

October 23, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: PRM PA Sheehan API#081-07750



**Photo#3:**

Absinth wormwood (State B list Noxious weed) is still evident, with new growth emerging at base of senesced plants..

October 23, 2020