

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/06/2020

Submitted Date:

11/09/2020

Document Number:

699601981**FIELD INSPECTION FORM**Loc ID 303044 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 38 PALMER CREST CTCity: SPRING State: TX Zip: 77381**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|------------------------------|-----------------------------|
| Dolezal, Pat | | pat.dolezal@ownresources.com | Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 252330 | WELL | PR | 05/15/1979 | GW | 125-06202 | BROPHY, T E 7 | PR |

General Comment:[Routine FIR](#)

Location

| | | | |
|--------------------|---------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | two track grassland | | |
| Corrective Action | | Date: | |

Overall Good: ☐

| | | | |
|----------------------|--------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Satisfactory | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|--------------|--|-------------|
| Emergency Contact Number: | | | |
| Comment: | Satisfactory | | |
| Corrective Action: | | | Date: _____ |

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: NA

☐ Multiple Spills and Releases?

| | | | |
|--------------------|-------------|-------|--|
| Fencing/: | | | |
| Type | PUMP JACK | | |
| Comment: | Steel panel | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------|---------------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Gas Meter Run | # 1 | | |
| Comment: | Calibration cert in place | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|----|-------|--|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | NA | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|----|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | NA | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 252330 | Type: | WELL | API Number: | 125-06202 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | GW | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | In Process | Other | In Process | | | |

Comment:

Use BMP's for erosion management

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT