

Final Reclamation Inspection

November 5, 2020

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 410164

Inspection Document #: 697502182

Weld County, CO

SENE Section 28 T3N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: FREDRIKSEN-63N68W /28SENE
Location ID: 410164



Photo 1. Photo taken from the northern plugged and abandoned well location, facing West. Photo illustrates the location is in-process of meeting Rule 1004 vegetative standards.

Inspection Photos
Location Name: FREDRIKSEN-63N68W /28SENE
Location ID: 410164



Photo 2. Photo taken from the northern plugged and abandoned well location, facing South. Photo illustrates some germination of desirable plant species. Appears the location has been mowed to control Russian thistle and Kochia.

Inspection Photos
Location Name: FREDRIKSEN-63N68W /28SENE
Location ID: 410164



Photo 3. Photo taken from the southern plugged and abandoned well location, facing West. Photo illustrates all equipment has been removed.

See comments under Photos 1-2 regarding revegetation.

Inspection Photos
Location Name: FREDRIKSEN-63N68W /28SENE
Location ID: 410164



Photo 4. Photo taken from the southern plugged and abandoned well location, facing North. See comments under Photos 1-2 regarding revegetation.