



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Columbine Springs 13-25-4-104 & 11C-25-4-104
API: 05-103-08545, 10748 Inspection: 700404106



39.68657, -109.0274, 6352.4ft, 39°
11/06/2020 03:25:24 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Location.

Columbine Springs 13-25-4-104 & 11C-25-4-104
API: 05-103-08545, 10748 Inspection: 700404106



39.68658, -109.02717, 6306.7ft, 351°
11/06/2020 03:25:43 PM



39.68662, -109.02713, 6294.1ft, 333°
11/06/2020 03:26:25 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Gas leak at pig station.

Columbine Springs 13-25-4-104 & 11C-25-4-104
API: 05-103-08545, 10748 Inspection: 700404106



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Valve can.

Columbine Springs 13-25-4-104 & 11C-25-4-104
API: 05-103-08545, 10748 Inspection: 700404106



39.68668, -109.02727, 6282.6ft, 248°
11/06/2020 03:28:19 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 6. Valve can.

Columbine Springs 13-25-4-104 & 11C-25-4-104
API: 05-103-08545, 10748 Inspection: 700404106



39.68669, -109.02721, 6284.1ft, 149°
11/06/2020 03:28:43 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 7. Riser in foreground.

Columbine Springs 13-25-4-104 & 11C-25-4-104
API: 05-103-08545, 10748 Inspection: 700404106