

Inspection Photos
Location Name: Beuten B #1
Spill/Release Point ID# 478491



Point source of Spill/Release Point ID #478491.



Area where fluids day lighted from Spill/Release Point ID #478491.

Inspection Photos
Location Name: Beuten B #1
Spill/Release Point ID# 478491



Fluid remaining in approximately 6' by 10' hole along ROW.



Unnamed drainage impacted by fluids from Spill/Release Point ID #478491.