

Inspection Photos  
Location Name: Beuten A #1  
API: 05-067-06800



API # on location sign is not accurate. Simcoe LLC listed as the operator of this location.



Stained soil along edge of concrete pad beneath prime mover.

Inspection Photos  
Location Name: Beuten A #1  
API: 05-067-06800



Unused equipment left on site.



Well head is wet and surrounding gravel is wet and stained.