

Inspection Photos

API: 071-07779

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 11/10/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07779 | Date: 11/10/2020

Inspection Photos



Photo 1. Facing southeast along the access road. There are multiple culverts along the road filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07779 | Date: 11/10/2020

Inspection Photos



Photo 2. The culvert is filled in with sediment causing stormwater to flow across the road causing this erosion. The culvert stick out far creating a drop of stormwater and there is no outlet protection.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07779 | Date: 11/10/2020

Inspection Photos



Photo 3. Facing northeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07779 | Date: 11/10/2020