

Inspection Photos

API: 071-09485

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 11/10/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09485 | Date: 11/10/2020

Inspection Photos



Photo 1. Facing southeast along the access road. The road has been regraded to divert stormwater toward the culvert.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09485 | Date: 11/10/2020

Inspection Photos



Photo 2. Facing northwest toward the location. The electric fence is in disrepair and needs maintenance. Corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09485 | Date: 11/10/2020