

Inspection Photos
Location#334823
Operator: Caerus
Inspection #: 692402343
Inspection Date: 10/30/20





Photo#1:
Overview of Location to North.

October 30,, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Schaffer Loc#334823



Photo#2:
West end of Location and adjacent, overlapping
Location.



Photo#3:
North Perimeter.

October 30., 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Schaffer Loc#334823