

Inspection Photos
Loc#334967
Operator: Caerus
Inspection #: 692402651
Inspection Date: 10/30/20





Photo#1:
Overview of Location to East. Insert & outline, area no longer needed for use.

October 30,, 2020



Photo#2:
Stormwater tunneling through sink holes off ditches
and pooling areas.




Photo#3:
Stormwater tunneling through sink holes off
ditches and pooling areas.

October 30., 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Benzel Loc#334967



Photo#4:
Stormwater tunneling through sink holes off ditches
and pooling areas.



Photo#5:
Stormwater tunneling through sink holes off
ditches and pooling areas.

October 30., 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Benzel Loc#334967



Photo#6:
Stormwater tunneling through sink holes off ditches
and pooling areas.

October 30., 2020



Photo#7:
Stormwater tunneling through sink holes off
ditches and pooling areas.