

Chaco Energy Company, Krause-Albin 1-20  
005-06478

Inspection #688308884

10/29/2020

PA Inspection, day two plus Cut/Cap pics from 11/20/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources



Colorado Oil and Gas Conservation Commission  
39.60526, -104.47089, 5853.0ft, 309°  
10/29/2020 08:57:03 AM

Krause Albin  
1-20



Tag @ 8'

Chaco Energy

Krause - Albin 1-20

API #

05-005-06478

NwNw 20-5s-63w-6

11-2-2020