

BP L48 San Juan



## V2 Compliance Follow Up Form

18160694147

**Reference Number:**

**Form Name:**

**Submitter Name:**

**Submission Date:**

**Location:**

20201030-18160694147

V2 Compliance Follow Up Form

Cole Nichols (colen@horizonenvservices.com) |  
colen@horizonenvservices.com

Oct 30, 2020 2:28:22 PM MDT

91 S Skylane Dr, Durango, CO 81303, USA

Oct 30, 2020 2:27:19 PM MDT [ [View Map](#) ]

## INFORMATION

### Section 1

<b>Name</b>	colen@horizonenvservices.com
<b>Date</b>	Oct 30, 2020
<b>Well Name</b>	MARTIN, JOE GAS UNIT 1
<b>API Number</b>	50670672400
<b>Select State</b>	Colorado
<b>Work type</b>	COGCC Inspection AR
<b>Action Complete</b>	Clean Up Weed Debris
<b>Photo of first corrective action completed</b>	



Completed work description Corrective  
Action 1

location sign

Photo of second corrective action completed





**Completed work description of corrective  
action 2**

before removal

**Photo of third corrective action completed**



**Completed work description of corrective action 3** after removal

**Photo of fourth corrective action completed**



**Completed work description** before removal

**Completed work description of corrective action 4** removed weed debris from site



**Additional photos**



**Additional photos**



**Completed work description**

**Summary of all work completed**

removed weed debris from site

previous treatment dates 7/21/16, 7/31/17,  
7/13/18, 10/29/19, 7/2/20