

**Inspection Photos**  
**Location Name: BP Beuten B #1**  
**API: 05-067-06725**



**Beuten B #1 location photo.**



**Beuten B #1 well head and artificial lift equipment.**

**Inspection Photos**  
**Location Name: BP Beuten B #1**  
**API: 05-067-06725**



**Lube oil container on secondary containment.**



**Stained gravel beneath Oil Lift equipment.**