

Inspection Photos
Loc#334864
Operator: Caerus
Inspection #: 692402645
Inspection Date: 10/30/20





Photo#1:

Overview of Location from entry to Southeast. Note pooling of stormwater.

October 30,, 2020



Photo#2:
Pooling of stormwater and rutting on pad.

October 30., 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus KRK Loc#334864