

Inspection Photos

Loc#334835

Operator: Caerus

Inspection #: 692402647

Inspection Date: 10/30/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry to North.

October 30,, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus KKK Loc#334835



Photo#2:
Pooling of stormwater.



Photo#3:
Interim area.

October 30,, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus KRK Loc#334835