

# *Inspection Photos*

*Loc#324031*

*Operator: Caerus*

*Inspection #: 692402648*

*Inspection Date: 10/30/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location from entry to South.

October 30,, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus KRK Loc#324031



Photo#2:  
View to North.

October 30,, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#3:  
View to Northwest.

Caerus KRK Loc#324031