

Inspection Photos
Location Name: Ute AA #4
API: 05-067-09668



Stained gravel around AA #4 well head.



Stained concrete pad and gravel beneath prime mover at the AA #4 pump jack.

Inspection Photos
Location Name: Ute AA #4
API: 05-067-09668



Stained gravel near lube oil container by the AA #4 well.



"Trapper" stuffing box containment device at the AA #1S.

Inspection Photos
Location Name: Ute AA #4
API: 05-067-09668



Staining present on concrete pad and near lube oil container.



Stained soil near lube oil container by the AA #1S well.