

Inspection Photos

Operator: BP America
API: 067-06785
Date: 11/10/2020



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is progressing with western wheatgrass, blue grama, sand dropseed, and smooth brome. Working areas are mowed.



Photo 3. View of the western project area from the northwestern corner facing southward.



Photo 4. View of reference area comprised of irrigated grass field, largely snow covered at this time.