

Inspection Photos

Operator: BP America
API: 067-09629
Date: 11/10/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing with grasses such as smooth brome, crested wheatgrass, intermediate wheatgrass. Approximately 300 musk thistles observed within the project area.



Photo 3. View of the southern project area from the southeastern corner facing westward.



Photo 4. View of reference area (beyond ditch) comprised of irrigated grass field, largely snow covered at this time.



Photo 5. View of closed gate after leaving location.