

Inspection Photos

Location Name: CAERUS PICEANCE LLC ORCHARD-68S96W /17SWSW

Location ID: 311752



Photo #2232 from entrance to location.




Photo #2235 Braden head valves are not accessible on well 17-13DT.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ORCHARD-68S96W /17SWSW

Location ID: 311752



Photo #2233 Tracking occurring from location to access road.



Photo #2234 Tracking occurring from location to access road.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ORCHARD-68S96W /17SWSW

Location ID: 311752



Photo #2236 Tracking occurring from location to access road.