

Inspection Photos  
Location Name: Silverton 4 North  
Location ID: 458676



Nov 12, 2020 at 9:11:47 AM  
+40.3406, -104.4510  
Weld

Colorado Oil & Gas Conservation Commission



Nov 12, 2020 at 9:56:10 AM  
+40.3409, -104.4476  
Weld

Colorado Oil & Gas Conservation Commission

Photo #1 Location

Photo #2 Drilling/Rig sign

# Inspection Photos

## Location Name: Silverton 4 North

### Location ID: 458676







Photo #3 BOP Test Charts

Photo #4 BOP Test

# Inspection Photos

Location Name: Silverton 4 North  
Location ID: 458676



**Photo #5 Drilling Permits**

**Photo #6 Current Well**