

Inspection Photos
Location Name: J P Weise 1
Location ID: 312773



Photo 1. Overview of location taken facing northeast. Dried annual weeds present.



Photo 2. Pit. Dried annual weeds present.

